



# **Hunters Point Radiological Program Update**

Hunters Point Naval Shipyard BCT Meeting May 26, 2011



### **Overview**




#### Radiological Project Work Overview

- Current Project Map
- SS/SD Removal and Building Survey Update
  - Crisp Rd.
  - Parcel C
  - Parcel E 500-Series
  - Parcel D-1
- Gun Mole Pier Stabilization Update



# **2011 Radiological Projects**







### Crisp Rd/Parcel E SS/SD Removals & Building Surveys



- Crisp Rd complete! Site restoration signed off!
- Bldg 810 CDPH performed Confirmation Survey on April 14
- Bldg 414 Final FSS submitted. Confirmation Survey June 9
- Site 701 Draft FSS submitted for Regulatory review May 6
- Site 704 Draft FSS submitted for Regulatory review May 25
- Bldg 707 Triangle Characterization and remediation of surface and trench contamination on-going
- IR-04 Scrap Yard Trench backfill required



# Parcel C Storm Drain & Sewer Removals



- SS/SD line removal commenced in Parcel C on January 4th
  - Excavated soil and pipe removal through May 13, 2011:
    - 11,895 linear feet of SS/SD lines removed
    - 20,805 cubic yards excavated
    - 2 Survey Units have been backfilled
    - 4 Survey Units currently being surveyed and sampled
    - 7 Survey Units awaiting offsite data prior to backfilling







# Parcel C Building Surveys



- Bldg 203- Complete removal of sewer lines, drafting TSP
- Bldgs 214, 241, 272- Surveys complete, data under internal review
- Bldg 271- Sewer removal underway
- North Pier- Delayed due to Pier Demo work



# Parcel C Asphalt & Concrete Recycling



 Commenced asphalt and concrete recycling on May 5; 10,600 tons of asphalt recycled through May 18







# Parcel C & Interior E Buildings/Sites Status






**Final** 

Draft

Internal Draft (Data under review)



Waiting for concurrence of Free-Release determination





#### Parcel E 500 Series



- Field Work
  - Site preparation activities continue
  - Continue asbestos abatement, fire-brick, and furnace removal activities in Building 521

 Completed asbestos abatement in Building 500





 Working with RASO on Draft TSPs for Former Building 503, 507, 509, and 517 Sites



# Impacted Building and Sites Within Parcel E 500 Series Area









### Status of Parcels B & G



- All Parcel B Building Surveys Complete
  - Building 140 Discharge Channel CDPH performed Confirmation Survey on April 13, 2011
  - Building 140 Tech Memo submitted for Regulatory review May 23
- Draft Parcel B RACR will be issued shortly after B140 Tech Memo is finalized
- Preparing response to regulatory comments on Draft Parcel G RACR



## **IR07/18 Modeling Update**



- The Draft Radiological Risk and Dose Modeling for Sites IR-7 and IR-18 is under Agency review
- The Navy has scheduled a meeting on June 8, 2011 in Sacramento with DTSC/CDPH to discuss



#### **Parcel D-1 Current Field Work Status**



- Gun Mole Pier
  - Remediated 3 survey Units with Cs-137, awaiting results of post remediation samples
- South Pier
  - Remediated 2 survey Units with Cs-137, awaiting results of post remediation samples
- Building 274
  - No detections above investigation Levels
  - Developing internal draft FSS Report



#### **Parcel D-1 Current Field Work Status**



- Building 383 Area
  - Completed building slab foundation and asphalt removal
  - Class 1 samples no elevated results; Class 2 awaiting analytical results
- Building 313,313A & 322 sites
  - Elevated levels of Cesium 137 and Radium 226
  - Remediation of an estimated 175 cu yds of soil
  - Post remediation samples had no detections
  - Systematic samples have been taken and are awaiting the lab results
- Storm Drain and Sanitary Sewer Removal
  - 85% complete (10,300 lineal ft)
  - 15 % remaining primarily in the RSY 2 footprint (1,800 lin. ft)
  - Awaiting final status survey offsite lab data to start trench backfill



# Parcel D-1 Upcoming Field Work




- Continue RAD surveys under the RSY 2 footprint
- Continue to remove remaining SS/SD lines in RSY 2 footprint
- Continue Develop and submit Survey Unit Project Reports (SUPRs)
- Begin backfilling trenches
- Install storm water swale on Manseau St
- Mobilize and perform asphalt grinding and site restoration



### **Pier Stabilization**







#### **Pier Stabilization**



- Stabilization work will be de-obligated from contract
- Scope to be revised to possibly include:
  - Radiological survey of Railroad ties (creosote)
  - T&D of Railroad ties
  - Additional SS/SD removal in D-1
  - NRDL Building Site Survey





Comments, Questions, Concerns ???